

## Case Study Cold Work – Handrail Repair

## Kits for Repairing Corroded Handrail Repairs

**Tested and Approved** 

Simple Step-by-Step Application

**Commercially Adaptable** 

Local & International Technical Support

All in One Kit – Including Housekeeping



info@protectolast.com



## Cold Work - Handrail Repair SKPS<sup>®</sup> Case Study



01- Surface Preparation

Prepare the surface to St2 or St3 standards, clean with Acetone/MEK, and mark with Multi-Surface Painter's Tape.



02- Compound on Anomaly Area

Pour hardener (part B) into part A, mix for at least 5 minutes, then brush anomaly with compound for a metal plate cushion.



03- Sleeve Application on Compound

Apply Protectolast SR, attach sleeve plate with wire, brush with compound, chamfer edges.



04- Glass Fiber Application

Cut two layers of glass fiber, spread compound, wrap over metal plates to cover anomaly.



**05- Final Application** 

Apply final Protectolst SR layer, cover with peel ply, and remove after 4hours of curing.



info@skps.com